


Diagnose-Adapter


#	PN	T1	T2	L1	S1	S2
SCA-1/4-EMA-3	1000 bar	1/4 BSPP	M16x2	32	27	22
SCA-1/2-EMA-3	630 bar	1/2 BSPP	M16x2	36	30	22
SCA-3/2-EMA-3-HP	1000 bar	1/2 BSPP	M16x2	36	32	22




SCA-EMA-3/1

Diagnose-Kupplung


#	PN	T1	T2	L1	S1	S2
SCA-EMA-3/1	630 bar	M16x2	--	37	17	--
SCA-EMA-3/2	630 bar	M16x2	S12x1.65	31	17	17
SCA-EMA-3/3	630 bar	M16x2	M16x2	43	17	--
SCA-EMA-3/4	630 bar	M16x2	M16x1.5	31	17	17




SCA-EMA-3/2



SCA-EMA-3/3



SCA-EMA-3/4



90° Diagnose-Adapter mit Messkupplung

#	PN	T1	T2	L1	L2	S1	S2
SCA-90-EMA-3	630 bar	M16x2	M16x2	49	26	19	22



Bitte Druckbereich beachten!